Safety Issue Type: Recalls

July 17 2026 NHTSA Campaign Number: 26C004000

Headrest Position May Shift in a Crash/FMVSS 213

A headrest that shifts unexpectedly may increase the risk of injury in a crash.

NHTSA Campaign Number 26C004000

Manufacturer Evenflo Company, Inc.

Components CHILD SEAT

Potential Number of Units Affected 59661

Summary

Evenflo Company, Inc. (Evenflo) is recalling certain Reo by Revolve360 child seats in color variants Nantucket, Danvers, Chelsea, Holden, Brookline, and Lenox. Please refer to Evenflo's recall report for the specific models. In certain rear or forward-facing positions, the headrest may shift position during a crash. As such, these child seats fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 213, "Child Restraint Systems."

Remedy

The remedy for this recall is currently under development. Interim letters, notifying owners of the safety risk, are expected to be mailed August 17, 2026. Additional letters will be sent once the remedy is available. Owners may contact Evenflo customer service at 1-800-233-5921.

Notes

Affected Products (1)

Child Seat

EVENFLO	REO BY REVOLVE 360	9999

Associated Documents (3)

Recall 573 Report - Jul 22, 2026
RCLRPT-26C004-6062.pdf 0.445KB
https://static.nhtsa.gov/odi/rcl/2026/RCLRPT-26C004-6062.pdf

Recall 573 Report
RCLRPT-26C004-1274.pdf 0.445KB
https://static.nhtsa.gov/odi/rcl/2026/RCLRPT-26C004-1274.pdf

RCAK - Recall Acknowledgement
RCAK-26C004-0949.pdf 0.321KB
https://static.nhtsa.gov/odi/rcl/2026/RCAK-26C004-0949.pdf